

ADULT DAY CARE & CHILD CARE FIRE INSPECTION REPORT

COUNTY Catawba DATE OF INSPECTION 08/21/2018 Facility ID # 1854414

Please complete all items below. If not applicable, check N/A in the box with a written explanation attached.

Name of Facility First Baptist Church - Hickory Adult _____ Child x

Address 339 2ND AVE NW Phone 704-740-8854

City Hickory Zip 28601 Responsible Party Donnie Saunders

GENERAL PRECAUTIONS:	YES	NO	N/A
1. Attic/basement/closets/garage/furnace room & heaters clear of trash & combustible materials.	X		
2. Clearance from ignition sources & combustible materials maintained.	X		

EMERGENCY PLANNING:	YES	NO	N/A
3. Approved evacuation plan posted.	X		
4. Evidence of monthly fire drills posted.	X		
5. Record of employee training in fire prevention/evacuation & annual fire safety training on site.	X		

FIRE SERVICE FEATURES:	YES	NO	N/A
6. Street Number posted. (Contrasting color to building & height 4" or more.)	X		
7. Unobstructed fire apparatus road. (Width of 20' & vertical clearance of not less than 13'6".)	X		
8. Hydrants/Fire Department connections/control valves clear of obstructions by 3'.			X

BUILDING SERVICES AND SYSTEMS:	YES	NO	N/A
9. Approved heating system, listed. (No fuel burning or portable electric space heaters.)	X		
10. Emergency lighting/exit lights in good operating order.	X		
11. Electrical panels clear of storage. (Minimum 30")	X		
12. Wiring/fixtures in good condition. (Extension cords not suitable for permanent wiring.)	X		
13. Type I hood system over all domestic cooking appliances that produce grease laden vapors.	X		

FIRE RESISTANCE RATED CONSTRUCTION:	YES	NO	N/A
14. Required fire resistant rating maintained. (Walls, partitions, floors)	X		
15. Door-hold open devices/automatic door closures operating properly.	X		

INTERIOR DECORATIONS & FURNISHINGS:	YES	NO	N/A
16. No storage of clothing/personal effects in corridors & lobbies.	X		
17. Maximum 10% of decorative materials covering walls. Does not apply to artwork & teaching material in classroom. Nothing suspended from ceiling.	X		
18. 20% maximum coverage for artwork & teaching material located on corridor walls.	X		
19. Exits free of obstructions.	X		

FIRE PROTECTION:	YES	NO	N/A
20. Sprinkler system maintained with annual test reports provided.			X
21. Smoke detector/fire alarm system maintained with annual test reports provided.	X		
22. Approved extinguishers mounted properly & in good working order.	X		
23. Cooking suppression systems & hood exhaust properly maintained.	X		
24. Protective guards (such as screens) on fuel burning furnaces or fireplaces provided.			X

MEANS OF EGRESS:	YES	NO	N/A
25. All exits & their access (i.e. Aisles & Corridors) free of obstructions.	X		
26. All locking devices on exit doors are of an approved type.	X		
27. Yards & fencing to allow unobstructed exit to exterior of site.	X		

Approved for day time care only Approved for day time and night care

At the time of this inspection, the fire safety conditions in this facility were: Satisfactory Unsatisfactory

Inspector TD Raper Phone 828-323-7522